

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

354
West
1/2-1
0.587 mi.
3100 ft.

VACANT SITE
2201 NEPTUNE AVE
BROOKLYN, NY

NY Spills S123662613
N/A

Relative:
Higher

Actual:
0 ft.

SPILLS:

Name: VACANT SITE
Address: 2201 NEPTUNE AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1900256 / Not Reported
Facility ID: 1900256
Facility Type: ER
DER Facility ID: 537435
Site ID: 586082
DEC Region: 2
Spill Cause: Other
Spill Class: D4
SWIS: 2401
Spill Date: 2019-04-08
Investigator: HSSEKHON
Referred To: Not reported
Reported to Dept: 2019-04-08
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 1
Date Entered In Computer: 2019-04-08
Spill Record Last Update: 2019-07-03
Spiller Name: Not reported
Spiller Company: PROPERTY OWNER
Spiller Address: Not reported
Spiller Company: 999
Contact Name: DANNY SINGH
DEC Memo: "DEC Piper spoke with Danny Singh at RSK Environmental. tanks were confirmed to be three (3) 550-gallon previously used gasoline underground storage tanks (USTs). One tank appeared in poor condition and gasoline impacted soil was identified on the northern section of the tanks. The site is currently being redeveloped and at this excavation activities are on hold until the tanks are removed. Tanks were registered with PBS and decommissioned. CSL Sent to : NJ Telecom Exchange Acquisition LLC c/o Promont 3611 14th Ave, Ste 606 Brooklyn, NY 11218 Attn: Israel Lerner 5/9 - Sekhon RSK Environmental submitted soil sample analysis report to DEC for review- Benz(a)anthracene - 670ug/kg Benzo(a)pyrene -720ug/kg Benzo(b)fluoranthene - 620ug/kg Benzo(ghi)perylene - 510ug/kg Benzo(k)fluoranthene - 520ug/kg Chrysene - 640ug/kg Fluoranthene - 1600ug/kg Indeno(1,2,3-cd)pyrene - 550ug/kg Pyrene - 1600ug/kg Chlorobenzene - 11000ug/kg Diesel Range Organics (c10-c28) - 1300ug/kg Iron - 14200 ug/kg Danny D. Singh Senior Environmental Consultant Tel: (718) 438-2200 Ext. 202 Cell: (347) 728-0768 danny@rskenvironmental.com 5/13 - Sekhon called Danny Singh to get updates. Sample results DECDOCs 5/24/19 - Sekhon Sample results discussed with DEC Piper, and are in acceptable range.
Decdocs. 6/19 - Sekhon Waiting for summary report. 7/2/ - Sekhon

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Remarks:

Summary report submitted. DECDOCs"
"3 ust - 550 gallon each - cleanup pending"

All Materials:

Site ID: 586082
Operable Unit ID: 1333754
Operable Unit: 01
Material ID: 2343011
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported